

Job Information

Job #:	97123				Date:	July 29, 2020
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	Sage V Foods		Reason:	
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

Name Plate Information

Manufacturer:	Baldor	Enclosure :	Totally Enclosed Fan Cooled
Serial#:	C1510290667	Model#:	
Service Factor:	1.15	Frame:	324TCZ
Horsepower/kW:	40	Rated RPM:	1775
Rated Amps:	98/46	Rated Voltage:	230/460
Phase:	3	Cycles:	60
Special design:	No		

Enclosure Type image



Nameplate

DE

ODE

F1

F2

Тор







WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes	Contaminant(s):	Water
Shaft rotation:	Bi-directional	Contaminant(s) Amt:	Other
Shaft grounding device present?:	No	Contaminant Image:	
Type of grounding device:			
Shaft runout(TIR-Inbound):			

Bearings DE:	Worn	Bearings DE make:	FAG
Insulated:	No	Bearing DE Size:	6312-2RS
Bearings ODE:	Worn	Bearings ODE make:	FAG
Bearing Type:	Ball	Bearing ODE Size:	6311-2RS
Bearings Retainer:	Yes	Thermal Protection:	No
Retainer condition:	Good	Thermal Protection Type:	_


Bearing Type Image



Bearing Make Image



Bearing Retainer Image



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Lubrication Type:	Grease	Thermal Protection device DE:	_
Lubrication brand inbound:	Mobile Polyrex EM	Thermal Protection device ODE:	_
Lubrication brand outbound:	Mobile Polyrex EM		
Grease Amt DE:	Full	Grease Cond. DE:	New
Grease Amt ODE:	Full	Grease Cond. ODE:	New
Seals DE type:	N/A		
Seals DE size:			
Seals DE (inbound) condition :			
Seals ODE type:	N/A		
Seals ODE size:			
Seals ODE (inbound) condition			
Shaft damage cause:	None	Shaft Image:	



VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Brg. Image:



Water jacket:	N/A		Fan:	Ok	Frame co	ond.:	Good
Motor Mount Positi	on: Horizontal/Fe	oot mount			Endbell type:	Singl	e piece
Missing parts?				Endbell Image:			
J-Box cover	O-rings	J-Box					
HH cover	Glands	V None				1 0	
Other missing par	ts						

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Pie	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
DE @ 0	ODE @ 0	_
DE @ 90	ODE @ 90	
DE @ 180	ODE @ 180	
DE @ 270	ODE @ 270	


AC Electrical Inspection

Number of leads:	3	Terminal Markings:				
Length of leads:	9in	REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Markings Identified By Color:				
Size of leads:		1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown		
Lead condition:	Good	4-Yellow	8-Red			
Lug type:		Connections As Re	eceived:			
Lug Condition:	_		Terminal	Lugs		
Lug size:						
Lug Attachment:	_					

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Winding cole Winding conditio		Winding ima	ige Winding Therr	mal Protection: No
Winding Therm Protection D				
Winding Therm Protection OD				
Stator test resul	ts: Rewind			
Megs incoming:	Good	Surge incoming: Go	od Hi-pot	t incoming: Good
Winding Resistan	ice Incoming			
	Phases A to B	Phases B to C	Phases C to A	Resistive imbalance
Incoming	0.00	0.00	0.00	
Leads/	jumpers: Ok		Lead jumper Image	». :
If other, leads/	jumpers:			
Mechanical	-			
·	and fasteners. Valid	ate correct fasteners.		

Bearings Retainer:

Bearing DE Size:

Bearing ODE Size:

Yes

6312

6311

Type of grounding device:

Shaft Condition:

Shaft runout(TIR-Inbound):

7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

Retainer condition:

Good

Good

CENTRAL ARKANSAS WEST TENNESSEE

6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254



Mechanical Inspection (Continued)

Seals DE condition :	None	Brg. Seats DE:	Good
Seals DE type:	N/A	If DE undersized, amt.:	
Seals DE size:		Brg. Seats ODE:	Good
Seals DE (inbound) condition :		If ODE undersized, amt.:	
Seals ODE condition :	None	Shaft damage:	ОК
Seals ODE type:	N/A		
Seals ODE size:		Bushings/sleeves DE:	Ok
Seals ODE (inbound) condition :		Bushings/sleeves ODE:	Ok
Endbell fits/damage:	Good	Foot/Flange condition:	Ok
Endbell DE size:	5.1190	Foot flatness:	Pass
Endbell DE insulated?:	_		stomer or EASA spec(<10%
Endbell ODE size:	size: 4.7253		
Endbell ODE insulated?:	_		



Conclusion

Component Failure

Windings and bearings

Cause of Failure

Short and water contamination

Comments

Recommend rewind and new bearings

Service Tech name: Cl

Chris wiley

Service Tech signature:

Christilie

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301