

## **Job Information**

Job #:	97268				Date:	September 2, 2020
Priority:	_	Authorized OT:	No	Authorized by:		

## **Customer Information**

Name:	Process and Power		Reason:	
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

## **Name Plate Information**

Manufacturer:	Ingersoll Rand	Enclosure :	Totally Enclosed Fan Cooled	Enclosure Type image
Serial#:	11824755	Model#:	Fall Cooleu	
Service Factor:	1.21	Frame:	280S/M	
Horsepower/kW:	150	Rated RPM:	1785	
Rated Amps:	168	Rated Voltage:	460	90
Phase:	3	Cycles:	60	
Special design:	No			

Nameplate

DE

ODE

F1

F2





Тор

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



### **Mechanical Inspection**

#### Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes	Contaminant(s):	Carbon
Shaft rotation:	Bi-directional	Contaminant(s) Amt:	Full
Shaft grounding device present?:	No	Contaminant Image:	
Type of grounding device:			
Shaft runout(TIR-Inbound):			



#### Bearing Type Image



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

#### Bearing Retainer Image



**Thermal Protection** 





# **Mechanical Inspection (Continued)**

Lubrication Type:	Grease	Thermal Protection device DE:	_
Lubrication brand inbound:	Mobile Polyrex EM	Thermal Protection device ODE:	_
Lubrication brand outbound:	Mobile Polyrex EM		
Grease Amt DE:	Full	Grease Cond. DE:	New
Grease Amt ODE:	Full	Grease Cond. ODE:	New
Seals DE type:	N/A		
Seals DE size:			
Seals DE (inbound) condition :			
Seals ODE type:	N/A		
Seals ODE size:			
Seals ODE (inbound) condition			
Shaft damage cause:	None	Shaft Image:	



VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



### **Mechanical Inspection (Continued)**

Brg. Image:



Bushings/sleeves image:



Water jacket: Ok



Fan:

Missing

Frame cond.: Good



Motor Mount Position:

Missing parts?

Horizontal/Foot mount



Single piece

40 Bas

V	J-Box cover	
	HH cover	

Endbell Image:





Other missing parts

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



## **Mechanical Inspection (Continued)**

Air Gap Meaurements (N/A on Single Pie	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
DE @ 0	ODE @ 0	_
DE @ 90	ODE @ 90	
DE @ 180	ODE @ 180	
DE @ 270	ODE @ 270	


## **AC Electrical Inspection**

Number of leads:	6	Terminal Markings:	1-6	
Length of leads:	6.5 feet	REF: NEMA Stds Markings Identifi	s. MG 1-2009, Rev. 1- ed By Color:	2010, 2.41-Terminal
Size of leads:		1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown
Lead condition:	Good	4-Yellow	8-Red	
Lug type:		Connections As Ree	ceived:	
Lug Condition:	Good	ſ	Terminal	Lugs
Lug size:				
Lug Attachment:	_			

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



#### **AC Electrical Inspection (Continued)**



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



## **AC Electrical Inspection (Continued)**

Winding color:	Like new	Winding	ı image	Winding Therma	I Protection:	Yes		
Winding condition :	Solid							
Winding Thermal Protection DE:	_							
Winding Thermal Protection ODE:	_							
Stator test results:	Salvageable							
Megs incoming: Go	od	Surge incoming:	Good	Hi-pot in	coming:	Good		
Winding Resistance Inc	coming							
Phase	es A to B	Phases B to C	Phase	s C to A	Resistive i	mbalance		
Incoming								
Leads/jumpe	ers: Ok							
If other, leads/jumpe	ers:							

## **Mechanical Inspection**

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition:	Good	Bearings Retainer:	Yes
Type of grounding device:		Bearing DE Size:	6316
Shaft runout(TIR-Inbound):		Bearing ODE Size:	6316

Retainer condition:

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

\_\_\_\_



# **Mechanical Inspection (Continued)**

Seals DE condition :	Worn	Brg. Seats DE:	Undersized
Seals DE type:	N/A	If DE undersized, amt.:	006
Seals DE size:		Brg. Seats ODE:	Good
Seals DE (inbound) condition :		If ODE undersized, amt.:	3.1497
Seals ODE condition :	Worn	Shaft damage:	ОК
Seals ODE type:	N/A		
Seals ODE size:		Bushings/sleeves DE:	Ok
Seals ODE (inbound) condition :		Bushings/sleeves ODE:	Ok
Endbell fits/damage:	Good	Foot/Flange condition:	Ok
Endbell DE size:	6.6929	Foot flatness:	Pass
Endbell DE insulated?:	No	Does Air Gap Meet Cu	stomer or EASA spec(<10%
Endbell ODE size:	6.6937	variation)?	
Endbell ODE insulated?:	No	_	

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



#### Conclusion

**Component Failure** 

**Cause of Failure** 

Comments

Wash and bake new bearings Repair DE shaft bearing fit De bearing had metal fatigue

Service Tech name:

Robert Wiley

Service Tech signature:

Jert Will

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301