

MECHANICAL EVALUATION

Job Information

Job #:	140493					August 29, 2019
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	HSLR		Reason:		
Contact:		Motor#:		PO#:	
Application:	_	Special notes:			

Name Plate Information

Manufacturer:		Enclosure :	Open Drop Proof (ODP)	Enclosure Ty	pe image
Serial#:		Model#:			
Service Factor:		Frame:			
Horsepower/kW:		Rated RPM:			
Rated Amps:		Rated Voltage:			
Phase:		Cycles:			
Special design:	No				
Nameplate	DE	ODE	F1	F2	Тор

WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



MECHANICAL EVALUATION

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	_	Shaft rotation:	_
Shaft grounding device present?:	No	Type of grounding device:	
Shaft runout(TIR-Inbound):		Bearings DE make:	SKF
Bearings DE:	Worn	Bearing DE Size:	6319
Insulated:	No	Bearings ODE make:	SKF
Bearings ODE:	Worn	Bearing ODE Size:	6314
Bearing Type:	Ball		
Bearings Retainer:	Yes		
Retainer condition:	_		

Bearing Type Image

Bearing Make Image

Bearing Retainer Image

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



MECHANICAL EVALUATION

Mechanical Inspection (Continued)

Seals DE type: Slinger

Seals DE size:

Seals DE (inbound) condition :

Seals ODE type: Slinger

Seals ODE size:

Seals ODE (inbound) condition :

Shaft damage cause: None

WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

MECHANICAL EVALUATION

Fan:

Ok

Frame

Frame cond.: Good

Motor Mount Position: Horizontal/Foot mount

Endbell type: Single piece

Other missing parts

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



MECHANICAL EVALUATION

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition:

: Damaged

_

Bearings Retainer: Yes

Bearing DE Size:

Bearing ODE Size:

Type of grounding device:

Shaft runout(TIR-Inbound):

Retainer condition:

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

6812 Lind Little Rock Phone 501 Fax 501-3



MECHANICAL EVALUATION

Mechanical Inspection (Continued)

Seals DE condition :	Worn	Brg. Seats DE:	Undersized
Seals DE type:	Slinger	If DE undersized, amt.:	005
Seals DE size:		Brg. Seats ODE:	Good
Seals DE (inbound) condition :		If ODE undersized, amt.:	
Seals ODE condition :	Worn	Shaft damage:	Salvageable
Seals ODE type:	Slinger		
Seals ODE size:		Bushings/sleeves DE:	Ok
Seals ODE (inbound) condition :		Bushings/sleeves ODE:	Ok
Endbell fits/damage:	Good	Foot/Flange condition:	Ok
Endbell DE size:	7.875	Foot flatness:	Pass
Endbell DE insulated?:	No		stomer or EASA spec(<10%
Endbell ODE size:	5.906	variation)?	
Endbell ODE insulated?:	No		

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



MECHANICAL EVALUATION

Conclusion

Component Failure

_

Cause of Failure

Comments

REWORK DRIVE END BEARING JOUYRNAL

Service Tech name: BILLY MAYS

Service Tech signature:

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301