



Infrared data indicates that 1 of the bus bars has a loose connection between the main breaker and the buss bar. Clean both bus bar surfaces and tight to correct torque.