

7030 Ryburn Dr. Millington, TN Phone: (901) 873-5300 Fax: (901) 873-5301 <u>www.gohispeed.com</u>

July 6, 2020

Cascades Tissue Memphis, TN

The following is a summary of findings from the July 2020 bi-weekly vibration survey of the Paper Machine. The Paper Machine was operating at around **3400** FPM during this month's survey.

QualiTest® uses a four step rating system for defects.

<u>Class I:</u> Defect is present, but effect on reliability is not clear; no immediate action is required. Continue to normally monitor.

<u>Class II:</u> Defect (s) present that may cause problem in long term (2-6 months). Repair during normal maintenance scheduling. Continue to monitor.

<u>Class III</u>; Defect (s) present that may cause failure in short term (less than 2 months). This should be addressed as soon as practical, with a high maintenance priority. Increase monitoring frequency.

<u>Class IV</u>; Defect (s) present that makes continued reliability unpredictable, and possibility of secondary damage is high. Repairs should be made ASAP. An unscheduled shutdown should be considered for repairs

Hi-Speed Industrial Service tests and inspects industrial machinery and equipment and makes recommendations concerning maintenance and repairs based on its experience in the field of industrial repair and maintenance. The information contained herein is provided as an opinion only, not as a quaranty or warranty of the matters discussed herein.

Defects

Reel Drum Bearings

Drum bearing data is showing some mechanical looseness especially the drive side bearing. Bearings should be need be inspected as time allows. We will monitor this closely. Rated as a **CLASS II** defect.

As always, it has been a pleasure to serve the Cascades Tissue Memphis, TN Plant. If there are any comments or questions, do not hesitate to contact us.

Sincerely,

ISO Certified Vibration Analyst, Category III

Kevin W. Mozwell



QualiTest_® Diagnostics

901-486-4565

kwilliam@gohispeed.com