

## D.C. Motor Maintenance Inspection Form

Job#: 95710

Date: 2 July 2019

Customer : Bridgestone

Machine: Strainer

Manufacturer: Reliance

Hp/kw: 300 ☒ Hp ☐ Kw

RPM: 1750/2000

Frame: C4011ATZ

Model #: ID#01kS590717G-YT

Serial #: No #



Internal visual appearance :

Dusty

Internal photo



Internal photo



Brushes :

100%

No. Of Brushes:

16

Brush Holders:

Good

Brush Springs:

Good

Brush holder



Brush photo



Commutator :

Good Mild wear

Stoned Com:

☐

Yes

☒

No


Comments :

Commutator is starting to groove. Brushes are wearing evenly.

Commutator



Commutator



Motor Evaluation :

Motor is slightly dusty. Commutator is starting to groove but not bad. Going to blow out motor and proceed with PDMA test.

Technician :

Trevor Hall

A handwritten signature in black ink, appearing to read 'Trevor Hall', is written above a horizontal line.