

Job Information

Job #: 142346 Date: April 23, 2020

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Nucor Reason:

Contact: Motor#: 142346 PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: Toshiba Enclosure : Open Drop Proof Enclosure Type image

(ODP)

Serial#: 8716465 Model#:

Service Factor: Frame:

Horsepower/kW: 52kw Rated RPM: 550

Volts 200 Volts 230

Amps Amps

Nameplate DE ODE F1 F2 Top

Fields



Armature













Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

> Shaft rotation: Contaminant(s) Amt: None

Shaft Condition: Contaminant Image: Good

Shaft grounding device

No present?:

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearing Type Image





Bearing Make Image



Bearing Retainer Image



Lubrication Type: Grease Thermal Protection device DE:

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE:


Lubrication brand outbound: Mobile Polyrex EM


> Grease Amt DE: Full Grease Cond. DE: New

Grease Amt ODE: Grease Cond. ODE: Full New



Mechanical Inspection (Continued)





Brg Image



Shaft Image



Brushing/sleeves



End bell



Water jacket: Ok



Fan: Ok



Frame cond.:



Good

Motor Mount Position: Horizontal/Foot mount

Foot/Flange condition: Ok Foot flatness: Pass



Mechanical Inspection (Continued)

Missing parts?					
☑ J-Box cover	O-rings	J-Box	HH cover	Glands	None
Other missing parts	Brush holder				
Air Gap Meaurements (N/A on Single Piece Endbell)				Does Air Gap Meet C spec(<10% variation)	
DE @ 0		ODE @ 0		-	
DE @ 90		ODE @ 90)		
DE @ 180		ODE @ 18	30		
DE @ 270		ODE @ 27	70		
Electrical Inspection	n				
☐ Move armature imbalance to Assemble			Commutator:	Salvageable	
Winding Inspection					
Meg Test IP to Flds: —		Polarity Check IP to Flds: —			
Meg Series to Shunt: -					

Brush Image:



DC Electrical Inspection

Brushes: Normal wear

Brush holders: Salvageable Qty.

Insulators: Salvageable Qty.

Salvageable Lead support stud: Alternate brush image: Qty.

Rocker ring: Salvageable Qty.





Commutator Type: Tig welded

Commutator Hardness: Good

Commutator Condition: Oil soaked

> Commutator Film: Ok

Commutator images





Armature type:

Factory

If other

Armature images

Failure mode:

Ok

If other

Failure location:

Other

If other

Armature condition:

Solid

If other

Winding color:

Still has color



DC Electrical Inspection (Continued)

Armature image

Armature Test Results

Megs: Good Hi-pot: Good Core loss: Good



Fields condition

Series/Stab condition: Ok Fields condition image:

Shunts condition: Ok

InterCoils condition: Ok



Fields test results

Series/Stab Meg: Ok Hi Pot: Ok Resistance: Ok

Shunts Meg: Ok Hi Pot: Ok Resistance: Ok

InterCoils Meg: Ok Hi Pot: Ok Resistance: Ok

Thermistors: In use Field Test image

RTD: In use At

Thermostat: Open





Leads/jumpers: Ok

Lead jumper Image:



Conclusion

Component Failure

None

Cause of Failure

None

Comments

Missing brush holder and two j- box covers need to pull armature out of the case to be clean shunts and inside case .

Service Tech name: Jesus

Service Tech signature:

Jul !