

Job Information

Job #: 143162 Date: August 17, 2020

Priority: 3 Authorized OT: No Authorized by: Terry f

Customer Information

Name: Container components Reason:

Contact: Motor#: PO#:

Application: Direct Drive Special notes:

Name Plate Information

Manufacturer: Ge Enclosure: Open Drop Proof Enclosure Type image

(ODP)

Serial#: 5cd223sa0478043 Model#: Cd506at

Service Factor: Frame: 506at

Horsepower/kW: 300 Rated RPM: 1750/1900

Volts 500 Volts 300

Amps 475 Amps 5

Nameplate DE ODE F1 F2 Top

Fields











Armature



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: No Contaminant(s): Grease

> Contaminant(s) Amt: Shaft rotation: Bi-directional Full

Shaft Condition: Contaminant Image: Other

Shaft grounding device

No present?:

Type of grounding device:

Shaft runout(TIR-Inbound):



Grease



Thermal Protection device DE:

Bearing Retainer Image

Unknown Thermal Protection device ODE:

Lubrication brand outbound: Unknown

Lubrication Type:

Lubrication brand inbound:

Grease Amt DE: Full Grease Cond. DE: Hard

Grease Amt ODE: Full

Thermal Protection




Thermal Overloads


Good

Grease Cond. ODE: Hard



Mechanical Inspection (Continued)





Brg Image



Shaft Image



Brushing/sleeves



End bell



Water jacket: N/A



Fan: N/A



Frame cond.: Good



Motor Mount Position:

Horizontal/Foot mount

Foot/Flange condition:

Ok

Foot flatness:

Pass



Mechanical Inspection (Continued)

Missing parts?		
☐ J-Box cover ☐ O-rings	J-Box HH cove	er Glands None
Other missing parts		
Air Gap Meaurements (N/A on Single Piece E	ndbell)	Does Air Gap Meet Customer or EASA spec(<10% variation)?
DE @ 0	ODE @ 0	_
DE @ 90	ODE @ 90	
DE @ 180	ODE @ 180	
DE @ 270	ODE @ 270	
Electrical Inspection		
☐ Move armature imbalance to Assemble	Commutator	: Salvageable
Winding Inspection		
Meg Test IP to Flds: Good	Polarity Check IP t	o Flds: Yes

Meg Series to Shunt:

Good



DC Electrical Inspection

Brushes: Normal wear Brush Image:

Brush holders:

Salvageable

Qty. 4

Insulators:

Salvageable

Qty.

Lead support stud:

Salvageable

Qty.

Alternate brush image:



Rocker ring:

Salvageable

Qty.

Commutator Type:

Soldered

Commutator images

Good

Commutator Condition:

Commutator Hardness:

Grooved

Commutator Film:

Smutty





Armature type:

Factory

If other

Armature images

Failure mode:

Ok

If other

Failure location:

Other

If other

Armature condition:

Solid

If other

Winding color:

Still has color

WEST TENNESSEE

7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

CENTRAL ARKANSAS

6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254



DC Electrical Inspection (Continued)

Armature image

Armature Test Results

Megs: Good Hi-pot: Good Core loss: Good



Fields condition

Series/Stab condition: Other Fields condition image:

Shunts condition: Shorted turn-turn

InterCoils condition: Ok



Fields test results

Series/Stab Meg: Ok Hi Pot: Ok Resistance: Ok

Shunts Meg: Bad Hi Pot: Bad Resistance: Bad

.....

InterCoils Meg: Ok Hi Pot: Ok Resistance: Ok

Thermistors: None Field Test image

RTD: None At

Thermostat: None





Leads/jumpers: Ok

Lead jumper Image:



Conclusion

Component Failure

Fields and bearings

Cause of Failure

Comments

Two different kinds of grease found in motor

On the drop test of the dc motor we found the field to be bad at 150 volts f1 70, f2 31, f3 27 and f 4 24 On INTERPOL's voltage drop shown at 24 volts I 1 4 v i2 4v i3 4v and i4 was 4v

Armature test - on the armature test meg ohms reading infinity (good)

On the armature bar to bar test with the electroum showed ok and pass all around the commutator. (Good)

Service Tech name: Terry f

Service Tech signature:

7

CENTRAL ARKANSAS