

Job Information

Job #:	94214				Date:	May 9, 2018
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	Bryce	Reason:		
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

Name Plate Information

Manufacturer: Ewhof		Enclosure :	osure : Open Drop Proof (ODP)		Enclosure Type image	
Serial#: 319720		Model#:				
Service Fa	actor:		Frame:			
Horsepower	r/kW:		Rated RPM:			
						
Armature	Volts 400 Amps 10.4		Fields	Volts 340		
				Amps 1.85		
Name	plate	DE	ODE	F1	F2	Тор
WEST TE	INNESS		ANSAS			

7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Yes
_
_
No

Shaft runout(TIR-Inbound):

Contaminant(s): Dirt Contaminant(s) Amt: Cup

Contaminant Image:



Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection


Not Available


—	Thermal Protection device DE:	Grease	Lubrication Type:
_	Thermal Protection device ODE:	Unknown	Lubrication brand inbound:
		Mobile Polyrex EM	Lubrication brand outbound:
New	Grease Cond. DE:	1/4	Grease Amt DE:
Other	Grease Cond. ODE:	1/4	Grease Amt ODE:

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)






Brg Image



Shaft Image



Brushing/sleeves







Water jacket: N/A

Fan: N/A Frame cond .:

Good







Motor Mount Position: Horizontal/Foot mount

Foot/Flange condition:

Ok

Foot flatness: Pass

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

	MILLIN	GTON, TN LITTLE ROCK, AR						
Mechanical Inspection (Continued)								
Missing parts?								
J-Box cover O-rings	J-Box HH cover	Glands None						
Other missing parts								
Air Gap Meaurements (N/A on Single Piece E	ndbell)	Does Air Gap Meet Customer or EASA spec(<10% variation)?						
DE @ 0	ODE @ 0	_						
DE @ 90	ODE @ 90							
DE @ 180	ODE @ 180							
DE @ 270	ODE @ 270							
Electrical Inspection								
Move armature imbalance to Assemble	Commutator:	Salvageable						

Winding Inspection


Meg Test IP to Flds: - Polarity Check IP to Flds: -

Meg Series to Shunt: -

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



DC Electrical Inspection








Commutator Type:	Soldered
Commutator Hardness:	Good

Commutator Condition : Oil soaked

Commutator Film: 0

Ok



Winding color: Li


Like new

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

Commutator images











DC Electrical Inspection (Continued) Armature Test Results							Armature image	
Megs:	Good	Н	i-pot:	Good	Core lo	SS:	Good	
Fields con	dition							
Ser	ies/Stab	condition:	Ok				Fields condition image	
	Shunts	condition:	Ok					
Ir	nterCoils	condition:	Ok					
Fields test	results							
S	eries/Sta	b Meg:	Ok		Hi Pot:	Ok	Resist	tance: Ok
	Shun	ts Meg:	Ok		Hi Pot:	Ok	Resist	tance: Ok
	InterCoi	ls Meg:	Ok		Hi Pot:	Ok	Resist	tance: Ok
Thermis	tors:	In use						Field Test image
F	RTD:	None				At		Not
Thermo	stat:	Closed						Not Available

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Leads/jumpers: Ok

Lead jumper Image:



Conclusion

Component Failure

Cause of Failure

Comments

TUC Commutator, replace brushes

Service Tech name: Lynn McDonald

Service Tech signature:

I)na

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301