

Job Information

Job #: 94311 Date: May 16, 2018

Priority: Authorized OT: No Authorized by:

Customer Information

Name: All American Polly Reason:

Contact: Motor#: PO#:

Application: Special notes:

Name Plate Information

Manufacturer: Enclosure: Open Drop Proof **Enclosure Type image** Us motors

(ODP)

Serial#: 98405-KY Model#: 36608452c55

Service Factor: Frame: 368AT

Horsepower/kW: 125 Rated RPM: 1750

Volts 500 Volts 300

> 200 2.5 **Amps** Amps

DE ODE F1

Fields

Nameplate F2 Top



Armature













Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): Other

> Shaft rotation: Bi-directional Contaminant(s) Amt: Other

Shaft Condition: Contaminant Image: Good

Shaft grounding device

Yes present?:

Type of grounding device: **Aegis**

Shaft runout(TIR-Inbound): 0.001



Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection

Not **Available**

Lubrication Type:

Grease

Thermal Protection device DE:

N/A

Lubrication brand inbound:

Mobile Polyrex EM

Thermal Protection device ODE:

N/A

Lubrication brand outbound:

Mobile Polyrex EM

Grease Cond. DE:

Hard

Grease Amt DE:

1/4


Grease Cond. ODE:


Hard

Grease Amt ODE: 1/4



Mechanical Inspection (Continued)





Brg Image



Shaft Image



Brushing/sleeves



End bell



Water jacket:

N/A

Fan:

N/A

Frame cond .:

Good

Not Available Not Available Not Available

Motor Mount Position:

Horizontal/Foot mount

Foot/Flange condition:

Ok

Foot flatness:

Pass



Mechanical Inspection (Continued)

Missi	ng parts?					
☐ J-E	Box cover	O-rings	☐ J-Box	☐ HH cover	Glands	✓ None
Other	missing parts					
Air Gap Meaurements (N/A on Single Piece Endbell)					Does Air Gap Me spec(<10% varia	et Customer or EASA tion)?
	DE @ 0		ODE @	@ 0	_	
	DE @ 90		ODE @	@ 90		
	DE @ 180			@ 180		
	DE @ 270			@ 270		
Electrica	al Inspect	tion				
☐ Mov	Move armature imbalance to Assemble		ble	Commutator: Salvageable		
Winding	Inspecti	on				
Meg Test IP to Flds: Good			I	Polarity Check IP to	Flds: Yes	
Meg Serie	s to Shunt:	Good				



DC Electrical Inspection

Brushes: Normal wear Brush Image:

Brush holders:

Salvageable

Qty. 8

Insulators:

Rocker ring:

Salvageable

Qty.

4

4

Alternate brush image:

Lead support stud:

Salvageable Salvageable

Qty.

Qty.

1

Not **Available**

Commutator Type:

Soldered

Commutator images

Commutator Hardness:

Good

Commutator Condition:

Stall marks

Commutator Film:

Black

Not Available

Armature type:

Factory

If other

Armature images

Failure mode:

Ok

If other

Failure location:

Other

If other

None

Armature condition:

Solid

If other

Winding color:

Like new

WEST TENNESSEE

7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

CENTRAL ARKANSAS

6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254



DC Electrical Inspection (Continued)

Armature image

Armature Test Results

Megs: Good Hi-pot: Good Core loss: Good



Fields condition

Series/Stab condition: Ok Fields condition image:

Shunts condition: Ok

InterCoils condition: Ok



Fields test results

Series/Stab Meg: Ok Hi Pot: Ok Resistance: Ok

Shunts Meg: Ok Hi Pot: Ok Resistance: Ok

InterCoils Meg: Ok Hi Pot: Ok Resistance: Ok

Thermistors: None Field Test image

RTD: None At

Thermostat: None





Leads/jumpers: Ok

Lead jumper Image:



Conclusion

Component Failure

None

Cause of Failure

None

Comments

Service Tech name: Dewey

Service Tech signature: