

### **Job Information**

Job #:	94825				Date:	October 18, 2018
Priority:	_	Authorized OT:	No	Authorized by:		

### **Customer Information**

Name:	Flake Board	Reason:		
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

### **Name Plate Information**

Manufacturer: Reliance		Enclosure : Open Drop Pr (ODP)		f	Enclosure Type image		
Serial#:		Model#:	6632564				
Service Fa	ctor:		Frame:				
Horsepower	/kW: 4	40	Rated RPM:	1750			
	Volts	240		Volts 240			
Armature	Amps	139	Fields	Amps 5.17	,		
Name	plate	DE	ODE	F1	F2	Тор	
VEST TE 7030 Ryburn		CENTRAL ARK	ANSAS				

7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254



None

None

#### **Mechanical Inspection**

#### Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes	Contaminant(s):
Shaft rotation:	Bi-directional	Contaminant(s) Amt:
Shaft Condition:	_	Contaminant Image:
Shaft grounding device present?:	No	
Type of grounding device:		
Shaft runout(TIR-Inbound):		

#### Bearing Type Image



#### Bearing Make Image



#### **Bearing Retainer Image**



#### Thermal Protection

Not Available




N/A	Thermal Protection device DE:	Grease	Lubrication Type:
N/A	Thermal Protection device ODE:	Mobile Polyrex EM	Lubrication brand inbound:
		Mobile Polyrex EM	Lubrication brand outbound:
Hard	Grease Cond. DE:	Full	Grease Amt DE:
Hard	Grease Cond. ODE:	Full	Grease Amt ODE:


WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



# MILLINGTON, TN LITTLE ROCK, AR

### **Mechanical Inspection (Continued)**





Brg Image



Shaft Image



Brushing/sleeves



End bell



Water jacket: N/A



Fan: N/A



Frame cond.:

: Good



Motor Mount Position:

Horizontal/Foot mount

Foot/Flange condition:

Ok

Foot flatness: Pass

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

	MILLIN	GTON, TN LITTLE ROCK, AR
Mechanical Inspection (Con	tinued)	
Missing parts?		
J-Box cover O-rings	J-Box HH cover	Glands 🔽 None
Other missing parts		
Air Gap Meaurements (N/A on Single P	iece Endbell)	Does Air Gap Meet Customer or EASA spec(<10% variation)?
DE @ 0	ODE @ 0	_
DE @ 90	ODE @ 90	
DE @ 180	ODE @ 180	
DE @ 270	ODE @ 270	
Electrical Inspection		

Move armature imbalance to Assemble Commutator: Salvageable

# Winding Inspection

Meg Test IP to Flds: Good Polarity Check IP to Flds: Yes

Meg Series to Shunt: Good

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



#### **MILLINGTON, TN** LITTLE ROCK, AR

#### **DC Electrical Inspection**







Commutator Type:	Soldered		
Commutator Hardness:	Good		

Commutator Condition : Streaked

Commutator Film:

Ok

Commutator images





Armature type:	Factory	If other
Failure mode:	Ok	If other
Failure location:	Other	If other
Armature condition:	Solid	If other

Winding color:

Like new

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

#### Armature images





## MILLINGTON, TN LITTLE ROCK, AR

DC Electrical Inspection (Continued)							A	rmature image	
Armature T	Good		i-pot:	Good	Core lo	ss:	Good		
Fields con	dition								
Ser	ries/Stab co	ondition:	Ok				Fields condition	image:	
	Shunts co	ondition:	Ok						
Ir	nterCoils co	ondition:	Ok						
Fields test	results								
S	Series/Stab	Meg:	Ok		Hi Pot:	Ok		Resistance:	Ok
	Shunts	Meg:	Ok		Hi Pot:	Ok		Resistance:	Ok
	InterCoils	Meg:	Ok		Hi Pot:	Ok		Resistance:	Ok
Thermis	tors: In	use						F	eld Test image
F	RTD: In	use				At			
Thermo	stat: O	pen							$ \int \varphi _{} w ds = \frac{2w E}{\left[\frac{2m}{N}\right]} \\ \left( \begin{bmatrix} m \\ m \\ 2 \end{bmatrix} \\ \left[ \frac{m}{2} \end{bmatrix} \right] \\ \left( \begin{bmatrix} m \\ m \\ m \end{bmatrix} \right) $

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Ok

# MILLINGTON, TN LITTLE ROCK, AR

Lead jumper Image:

Not Available

## Conclusion

Leads/jumpers:

**Component Failure** 

DE AND ODE SHAFT AND KEY WAY

#### **Cause of Failure**

Found Frosting on Both BEARINGS

#### Comments

Wash and bake new brushes Ageis ring ceramic bearing repair DE ODE SHAFTS AND Key WAYS

Service Tech name: Robert Wiley

Service Tech signature:

No la

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301