

Job Information


| Job #: | 95767 | | | | Date: | July 25, 2019 |
|-----------|-------|----------------|----|----------------|-------|---------------|
| Priority: | _ | Authorized OT: | No | Authorized by: | | |

Customer Information

| Name: | Jerry Walker &Sonw | | Reason: | | |
|--------------|--------------------|----------------|---------|------|--|
| Contact: | | Motor#: | | PO#: | |
| Application: | _ | Special notes: | | | |

Name Plate Information

| Manufacturer: | | Baldor | Enclosure : | Open Drop Proof (ODP) | Enclosure Type image |
|---------------------|----------|-----------------------|-------------|--------------------------|----------------------|
| Serial#: | | S9118177-001002F Q | Model#: | CDMG | |
| Service Factor: | | | Frame: | 288AT | |
| Horsepower/kW: 20KW | | 20KW | Rated RPM: | 1750 | |
| | Volt | s 230 | | Volts 230 | _ |
| Armature | V013 200 | Fields | V013 230 | | |
| | Amps 87 | | | Amps 1.8 | _ |
| | | | | | |
| | | | | | |



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

| Does the shaft turn freely?: | Yes |
|-------------------------------------|------|
| Shaft rotation: | CW |
| Shaft Condition: | Good |
| Shaft grounding device present?: | No |
| Type of grounding device: | |
| Shaft runout(TIR-Inbound): | |

| Contaminant(s): | None |
|---------------------|------|
| Contaminant(s) Amt: | None |
| Contaminant Image: | |





| Bearing Type Image | Bearing Make Image | Bearing Retainer Image | Thermal Protection |
|-----------------------------|--------------------|--------------------------------|--------------------|
| | | | Not Available |
| Lubrication Type: | Grease | Thermal Protection device DE: | _ |
| Lubrication brand inbound: | Mobile Polyrex EM | Thermal Protection device ODE: | _ |
| Lubrication brand outbound: | Mobile Polyrex EM | | |
| Grease Amt DE: | Full | Grease Cond. DE: | Charred |
| Grease Amt ODE: | Full | Grease Cond. ODE: | New |
| | | | |

WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)





Brg Image



Shaft Image



Brushing/sleeves

Not Available



Water jacket: Ok



Fan: Ok



Frame cond.:

: Good

End bell



Motor Mount Position:

Horizontal/Foot mount

Foot/Flange condition:

Ok

Foot flatness: Pass

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

| | | MILLING | STON, TN | LITTLE ROCK, AR | | | | | |
|--|-----------|------------------------------------|---------------------------------|-----------------|--|--|--|--|--|
| Mechanical Inspection (Continued) | | | | | | | | | |
| Missing parts? | | | | | | | | | |
| ☐ J-Box cover ☐ O-rings ☐ | J-Box | HH cover | Glands | Vone | | | | | |
| Other missing parts | | | | | | | | | |
| Air Gap Meaurements (N/A on Single Piece E | | Does Air Gap Me spec(<10% varia | eet Customer or EASA ation)? | | | | | | |
| DE @ 0 | ODE @ 0 | | _ | | | | | | |
| DE @ 90 | ODE @ 90 | | | | | | | | |
| DE @ 180 | ODE @ 180 | | | | | | | | |
| DE @ 270 | ODE @ 270 | | | | | | | | |
| Electrical Inspection | | | | | | | | | |
| Move armature imbalance to Assemble | С | Commutator: | _ | | | | | | |
| Winding Inspection | | | | | | | | | |

Yes

Meg Test IP to Flds: Good Polarity Check IP to Flds:

Meg Series to Shunt: Good

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



DC Electrical Inspection

| Brushes: | Normal wear | | | Brush Image: |
|--------------------|-------------|------|---|------------------------|
| Brush holders: | Salvageable | Qty. | 4 | |
| Insulators: | Salvageable | Qty. | 2 | |
| Lead support stud: | Salvageable | Qty. | 1 | Alternate brush image: |
| Rocker ring: | Salvageable | Qty. | 1 | |






| Commutator Type: | Soldered |
|------------------------|---------------------|
| Commutator Hardness: | Good |
| Commutator Condition : | Burned between bars |
| | |

Commutator Film:

Ok







Armature type: Factory If other Failure mode: If other Ok Failure location: Other If other Armature condition: Solid If other

Winding color:

Like new

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

Armature images





| DC Electrical Inspection (Continued) | | | | | | | | Armature image |
|--------------------------------------|---------------------|--------|-------|------|---------|-----|-------------------------|------------------|
| Armature Te | est Results Good | Hi | -pot: | Good | Core lo | ss: | Good | |
| Fields cond | | | | | | | | |
| Seri | es/Stab cond | ition: | Ok | | | | Fields condition image: | |
| | Shunts cond | ition: | Ok | | | | | |
| In | terCoils cond | ition: | Ok | | | | | |
| Fields test r | results | | | | | | | |
| Se | eries/Stab | Meg: | Ok | | Hi Pot: | Ok | Resistance | : Ok |
| | Shunts | Meg: | Ok | | Hi Pot: | Ok | Resistance | : Ok |
| | InterCoils | Meg: | Ok | | Hi Pot: | Ok | Resistance | : Ok |
| Thermiste | ors: None | 9 | | | | | F | Field Test image |
| R | TD: None |) | | | | At | | Not |
| Thermos | stat: None |) | | | | | | Available |

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Leads/jumpers: Ok

Lead jumper Image:



Conclusion

Component Failure

DE end bell housing fit bad armature shorted

Cause of Failure

Comments

Found frosting in DE bearing

Service Tech name: Robe

Robert Wiley

Service Tech signature:

Ber Wiley

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301