

Job Information

Job #:	96573				Date:	February 25, 2020
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	Kimberly Clark		Reason:		
Contact:		Motor#:		PO#:	
Application:	_	Special notes:			

Name Plate Information

Manufacturer: Reliance Serial#:		Enclosure : Model#:	Open Drop Proof (ODP) 01KA897420-RX	Enclosure Type image	
Service Factor:			Frame:		A CONTRACTOR
Horsepower/kW: 200		Rated RPM:	1750/1950		
Armature	ure Volts 500 Amps 322		Fields	Volts 300 Amps 3.61	-



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes
Shaft rotation:	Bi-directional
Shaft Condition:	_
Shaft grounding device present?:	Yes
Type of grounding device:	Ageis ring
Shaft runout(TIR-Inbound):	

Bearing Type Image



Bearing Make Image



Lubrication Type:	Grease
Lubrication brand inbound:	Mobile Polyrex EM
Lubrication brand outbound:	Mobile Polyrex EM
Grease Amt DE:	Full
Grease Amt ODE:	Full

Contaminant(s): None Contaminant(s) Amt: None

Contaminant Image:

Bearing Retainer Image



Thermal Protection





Thermal Protection device DE:	-
Thermal Protection device ODE:	_
Grease Cond. DE:	New
Grease Cond. ODE:	New

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)





Brg Image



Shaft Image



Brushing/sleeves



End bell



Water jacket: N/A



Fan: N/A



Frame cond.:

: Good



Motor Mount Position:

Horizontal/Foot mount

Foot/Flange condition:

Ok

Foot flatness: Pass

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

	MILLIN	IGTON, TN LITTLE ROCK, AR						
Mechanical Inspection (Continued)								
Missing parts?								
J-Box cover O-rings] J-Box 🗌 HH cove	r 🗌 Glands 🗌 None						
Other missing parts								
Air Gap Meaurements (N/A on Single Piece E	Endbell)	Does Air Gap Meet Customer or EASA spec(<10% variation)?						
DE @ 0	ODE @ 0	_						
DE @ 90	ODE @ 90							
DE @ 180	ODE @ 180	ODE @ 180						
DE @ 270	ODE @ 270	E @ 270						
Electrical Inspection								
Move armature imbalance to Assemble	Commutator	_						
Winding Inspection								
Meg Test IP to Flds: – Polarity Check IP to Flds: –								

Meg Series to Shunt: -

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



DC Electrical Inspection







Commutator Type: Tig welded Commutator Hardness: Good

Commutator Condition : Grooved

Commutator Film: 0

Armature type:

Failure mode:

Failure location:

Armature condition:

Ok

Factory

Front V ring

Ok



If other

If other

If other

If other

Commutator images



Armature images



Winding color: L

Like new

Solid

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



DC Electrical Inspection (Continued)							,	Armature image
Armature Test Results								
Megs:	Good	Н	i-pot:	Good	Core lo	oss:	Good	
Fields condi								
Serie	es/Stab condit	ion:	Ok				Fields condition image:	
	Shunts condit	ion:	Ok					
Int	erCoils condit	ion:	Ok					
Fields test r	esults							
Se	eries/Stab	Meg:	Ok		Hi Pot:	Ok	Resistance	: Ok
	Shunts	Meg:	Ok		Hi Pot:	Ok	Resistance	: Ok
I	InterCoils	Meg:	Ok		Hi Pot:	Ok	Resistance	: Ok
Thermisto	ors: In use	1					I	Field Test image
R1 Thermos	ГD: In use tat: Open	1				At		

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Leads/jumpers: Ok

Lead jumper Image:



Conclusion

Component Failure

Cause of Failure

Comments

De bearing has flutting due to Ageis ring packed with grease and product also brushes need replaced

Service Tech name: Rober

Robert Wiley

Service Tech signature:

() ile 27

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301