

## **Job Information**

Job #:	142276	Date:	April 10	, 2020
--------	--------	-------	----------	--------

Priority: — Authorized OT: No Authorized by:

#### **Customer Information**

Name: Mauser Location: Contact:

## **Name Plate Information**

Manufacturer: Rossi Ratio:

Serial#: Type:

Model#: Horsepower/kW: 0.55 /0.65

Input Speed: Output Speed:

Application ID: Coupling Type:

Wear

# **Gearbox Visual Inspection**

		-	
Oil:	Unacceptable	Unacceptable	Unacceptable
Gears:	Unacceptable	Unacceptable	Unacceptable
Seals:	Unacceptable	Unacceptable	Unacceptable

**Physical** 

**Contaminants** 



# **Gearbox Inspection (Continued)**















# **Gearbox Inspection (Continued)**

Environmental Conditions : Severe/Hostile Ambient Temperature :

Signs of excessive heat: No Humidity :

Signs of lubricant leaks: No Gearbox temperature :

Moisture present: No

# **Gearbox Inspection & Evaluation Checklist**

Primary drive rotates input shaft in correct direction	Yes
2. Condition of machinery guards if present	Not Present
3. Condition of coupling guards	Present/Acceptable
4. Type of coupler	
5. Condition of coupler	Present/Acceptable
6. Coupling Alignment	
7. Condition of housing	Acceptable
8. Condition of mounting hardware	Acceptable
9. Breather vent (ventilator) installed	Present/Acceptable
10. Condition of piping & connections(if forced lube system installed)	Present/Acceptable



# **Gearbox Inspection & Evaluation Checklist (Continued)**

11. Condition of switches, alarms, heaters, coolers, or other devices	Not Present	
12. Condition of inspection covers	Present/Acceptable	
13. Condition of seals & bearings	Damaged	
14. Gearbox oil level	Unacceptable	
15. Type & grade of specified lubricant		
16. Correct type & grade of specified lubricant	Unknown	
17. Appearance of lubricant	Contaminated	
18. Free rotation of shafts	Yes	
19. Condition of input shaft	Acceptable	
20. Endplay of input shaft		
21. Condition of output shaft	Acceptable	
22. Endplay of output shaft		
23. Gear backlash	Acceptable	




## **Gearbox Inspection & Evaluation Checklist (Continued)**

24. Gear tooth condition Damaged

25. Degree of wear Severe

26. Gear tooth contact Severe

#### 27. Identify type of gear tooth contact



Typical Contact Patterns for Double Helical Gears



## **Gearbox Comments**

Upon inspection of this unit we found , input gear damaged and motor input gear damaged. Gearbox oil was contaminated replace input shaft gear ,motor input gear,bearings and seals.motor surge test good. DE end bell was broken at the time of dismantling needs to be replace .

## **Conclusion**

Service Tech name: Jesus

Service Tech signature:

App'