

### **Job Information**

Job #:	142368				Date:	April 29, 2020
Priority:	_	Authorized OT:	No	Authorized by:		
Customer	Information					
Name:	Cleveland tram rail	Location:		Cor	ntact:	
Name Plat	te Information					
Manufacturer:	Cleveland			Ratio:		
Serial#:				Type :		
Model#:			Hors	sepower/kW:		
Input Speed:			O	utput Speed:		
Application ID:			Co	upling Type:		

# **Gearbox Visual Inspection**

	Wear	Physical	Contaminants
Oil:	Unacceptable	Unacceptable	Unacceptable
Gears:	Unacceptable	_	_
Seals:	_	_	_



# **Gearbox Inspection (Continued)**















# **Gearbox Inspection (Continued)**

Environmental Conditions :	Severe/Hostile	Ambient Temperature:
----------------------------	----------------	----------------------

Signs of excessive heat: No Humidity:

Signs of lubricant leaks: Yes Gearbox temperature :

Moisture present: Yes

# **Gearbox Inspection & Evaluation Checklist**

Primary drive rotates input shaft in correct direction	Yes
2. Condition of machinery guards if present	Not Present
3. Condition of coupling guards	Present/Acceptable
4. Type of coupler	None
5. Condition of coupler	Not Present
6. Coupling Alignment	
7. Condition of housing	Acceptable
8. Condition of mounting hardware	Acceptable
9. Breather vent (ventilator) installed	Not Present
10. Condition of piping & connections(if forced lube system installed)	Not Present

Not Present



# **Gearbox Inspection & Evaluation Checklist (Continued)**

11. Condition of switches, alarms, heaters, coolers, or other devices

11. Condition of switches, alarms, neaters, coolers, or other devices	Not i lesent
12. Condition of inspection covers	Not Present
13. Condition of seals & bearings	Unacceptable
14. Gearbox oil level	N/A
15. Type & grade of specified lubricant	
16. Correct type & grade of specified lubricant	Unknown
17. Appearance of lubricant	(See notes)
18. Free rotation of shafts	Yes
19. Condition of input shaft	Damaged
20. Endplay of input shaft	
21. Condition of output shaft	Unacceptable
22. Endplay of output shaft	
23. Gear backlash	Acceptable




### **Gearbox Inspection & Evaluation Checklist (Continued)**

24. Gear tooth condition Unacceptable

25. Degree of wear Mild

26. Gear tooth contact Damaged

#### 27. Identify type of gear tooth contact



Typical Contact Patterns for Double Helical Gears



#### **Gearbox Comments**

Replace bearings, shaft gear .weld crack n housing roller pin bracket. Replace shaft gear , due to water on teeth.

## Conclusion

Service Tech name: Jesus

Service Tech signature:

