

I.F.F Visual Inspection Electrical

The following items was found during the
infrared scan




MCC

51

Exhaust Fan MCC 29 needs to be
cleaned for air flow

Disconnect needs cleaned




MCC P3 Bucket

115 needs
cleaned



MSP Sharples #8 C.T's need to be
installed



North P1 MCC 3 Bucket #68



Substation 11 All fans need replaced



MCC P3 bucket 16

The following Substations need fans replaced

Substation 1 needs 3 fans

Substation 2 needs 1 fan

Substation 4 needs 3 fans

Substation 7 needs 2 fans

Substation 10 needs 3 fans

Substation 11 needs 8 fans

Substation 15 needs 2 fans

Substation 16 needs 1 fans