



MILLINGTON, TN

December 31, 2020

Post

Subject: New Roof Fan

The new roof fan vibration analysis performed on December 29th indicated the fan balance was at or below the specification for type and speed, about 1 mil p-p. Supporting data follows.

Hi-Speed Industrial Service tests and inspects industrial machinery and equipment and makes recommendations concerning maintenance and repairs based on its experience in the field of industrial repair and maintenance. The information contained herein is provided as an opinion only, not as a guaranty or warranty of the matters discussed herein.

This completes our assessment of your equipment for this survey. Thank you for your business and do not hesitate to call if you have any comments or questions.

Sincerely,

David W Shook

David W. Shook
Senior Reliability Specialists
Hi-Speed Industrial Service
dshook@gohispeed.com

