


DANGER:
UNLESS HOOK RAISES WHEN "UP" BUTTON IS PRESSED SEVERE HOIST DAMAGE AND A DROPPED LOAD MAY RESULT.
CORRECT IMPROPER HOOK DIRECTION BY INTERCHANGING INPUT POWER L1 AND L3
DO NOT CHANGE PUSHBUTTON WIRING.

WARNING
THIS EQUIPMENT MUST BE EFFECTIVELY GROUNDED ACCORDING TO APPLICABLE CODES.

AVERTISSEMENT
CET EQUIPMENT DOIT ETRE MIS A'LA TERRE EN ACCORDANCE AVEC LES NORMES EN VIGUEUR.

| NO. | CHANGE | DATE | ITL. | WIRING DIAGRAM |
|---|---|---|---|---|
| | | | | 3 PHASE 2-SPEED |
| | | | | D.C. SOLENOID BRAKE |
| | | | | BUDGIT ELECTRIC HOIST |
| | | | | SC. ------ |
| | | | | DA. 7/19/04 |
| | | | | DR. RITTER |
| | | | | CK. |

YALE • LIFT-TECH
division of Columbus McKinnon Corporation
Muskegon, Michigan 49443

SHEET 4 OF 4 SHEETS

333173

FROM 330565 SHEET 4