LR Field Services

Prepared for Koppers Company (10178)

2201 Edmonds
N. Little Rock AR 72117

Table of Contents

Field Service Ticket **1.0**

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 103204
FormID: 20960656

Koppers Company (10178)
2201 Edmonds
N. Little Rock, AR 72117

Job Information

1.	Hi-Speed Job Number	**103204**
2.	Asset Type	**Pumps**
3.	Make	
4.	Model	
5.	Serial Number	
6.	Customer Asset ID/Asset Name	

Service Call Details

7. Service Objectives

Disassemble, inspect, change out seals, reassemble and laser align.

8. Services Performed

Removed both pumps, brought back to shop to take off front end of pumps. Replaced seals, reinstalled impellers and took back to koppers. Reinstalled pumps.

9. Service Technician Recommendations

Approval Signatures

10. Service Technician Signature — **Trevor Hall**

11. Customer Signature — **Keon Talbert**

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.