




DANGER:
UNLESS HOOK RAISES WHEN "UP" BUTTON IS PRESSED SEVERE HOIST DAMAGE AND A DROPPED LOAD MAY RESULT.
CORRECT IMPROPER HOOK DIRECTION BY INTERCHANGING MOTOR LEADS ORANGE (5) & RED (8).
DO NOT CHANGE PUSHBUTTON WIRING.

WARNING
THIS EQUIPMENT MUST BE EFFECTIVELY GROUNDED ACCORDING TO APPLICABLE CODES.

AVERTISSEMENT
CET EQUIPEMENT DOIT ETRE MIS A LA TERRE EN ACCORDANCE AVEC LES NORMES EN VIGUEUR.

NO.	CHANGE	DATE	ITL.	ELEMENTARY DIAGRAM WITH TRANSFORMER
				1 PHASE RECONNECTABLE, STEARNS REVERSING SWITCH
				D.C. SOLENOID BRAKE
				BUDGET ELECTRIC HOIST
				SC. -----
				DA. 2/7/90
				DR. BES
				CK.
				SHEET 3 OF MORE SHEETS
				330174