




**DANGER:**

UNLESS HOOK RAISES WHEN "UP" BUTTON IS PRESSED SEVERE HOIST DAMAGE AND A DROPPED LOAD MAY RESULT. CORRECT IMPROPER HOOK DIRECTION BY INTERCHANGING INPUT POWER L1 AND L3 DO NOT CHANGE PUSHBUTTON WIRING.

**WARNING**

THIS EQUIPMENT MUST BE EFFECTIVELY GROUNDED ACCORDING TO APPLICABLE CODES.

**AVERTISSEMENT**

CET EQUIPEMENT DOIT ETRE MIS A LA TERRE EN ACCORDANCE AVEC LES NORMES EN VIGUEUR.

| NO. | CHANGE | DATE | ITL. | WIRING DIAGRAM        |
|-----|--------|------|------|-----------------------|
|     |        |      |      | 3 PHASE 2-SPEED       |
|     |        |      |      | D.C. SOLENOID BRAKE   |
|     |        |      |      | BUDGIT ELECTRIC HOIST |
|     |        |      |      | SC. -----             |
|     |        |      |      | DA. 7/19/04           |
|     |        |      |      | DR. RITTER            |
|     |        |      |      | CK.                   |
|     |        |      |      | SHEET 4 OF 4 SHEETS   |
|     |        |      |      | 333173                |