
1998 W Buss 4 Bucket R1



Measurements	
Sp1	102.3 °F
Sp2	87.0 °F
Parameters	
Emissivity	0.95
Refl. temp.	49 °F

Infrared data indicates that Phase B fuse $\,$ is operating at 20* higher than phase A and C . Clean fuse holder and replace all 3 fuses with matching fuse brand and amprage ratings .