

LR Field Services

Prepared for Almatris Inc/RCP Bauxite (10014)

4701 Alcoa Road
Bauxite AR 72011

Table of Contents

Field Service Ticket

1.0

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 04/22/2024

Powered by [INSPECTALL](#)

Table of Contents



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

Almatis Inc/RCP Bauxite (10014)
4701 Alcoa Road
Bauxite, AR 72011

FolderID: 102806
FormID: 20143549

Job Information

- | | |
|------------------------|------------------------------|
| 1. Hi-Speed Job Number | 102806 |
| 2. Asset Type | Siemens air compressor motor |
| 3. Make | Siemens |
| 4. Model | |

*New motor first holes 10.25" second are 12.25. 14.25" wide
Old motor first holes 10.75" second are 13.75" 16" wide*



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



5. Serial Number

6. Customer Asset ID/Asset Name

Service Call Details

7. Service Objectives

Remove motor

8. Services Performed

Removed motor and looked at a motor base customer wants replaced.

9. Service Technician Recommendations

Approval Signatures

10. Service Technician Signature

Trevor Hall

11. Customer Signature

James Sherrill