

LR Field Services

Prepared for Almatris Inc/RCP Bauxite (10014)

4701 Alcoa Road
Bauxite AR 72011

Table of Contents



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300


Field Service Ticket

FolderID: 103754
FormID: 22261984

Almatis Inc/RCP Bauxite (10014)
4701 Alcoa Road
Bauxite, AR 72011

Job Information

- | | |
|------------------------|------------------|
| 1. Hi-Speed Job Number | 103754 |
| 2. Asset Type | Ball mill |
| 3. Make | |



- | | |
|---------------------------------|---------------------|
| 4. Model | |
| 5. Serial Number | |
| 6. Customer Asset ID/Asset Name | A2 ball mill |

Service Call Details

- | | |
|---------------------------------------|--|
| 7. Service Objectives | <i>Set clearance on pinion. Laser align gearbox to pinion and motor to gearbox.</i> |
| 8. Services Performed | <i>Set pinion. Attempted to align the rest but customer decided to stop and go a different route. Customer is going to replace pinion and couplings and have us come back out.</i> |
| 9. Service Technician Recommendations | |

Approval Signatures

- | | |
|---|--------------------|
| 10. Service Technician Signature | Trevor Hall |
|  | |
| 11. Customer Signature | David Wolfe |

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

D-2 N.1 F