

LR Field Services

Prepared for Almatris Inc/RCP Bauxite (10014)

4701 Alcoa Road
Bauxite AR 72011

Table of Contents

Field Service Ticket	1.0
Field Service Ticket	2.0



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 103754
FormID: 22261984

Almatis Inc/RCP Bauxite (10014)
4701 Alcoa Road
Bauxite, AR 72011

Job Information

- | | |
|------------------------|-----------|
| 1. Hi-Speed Job Number | 103754 |
| 2. Asset Type | Ball mill |
| 3. Make | |



- | | |
|---------------------------------|--------------|
| 4. Model | |
| 5. Serial Number | |
| 6. Customer Asset ID/Asset Name | A2 ball mill |

Service Call Details

- | |
|--|
| 7. Service Objectives |
| <i>Set clearance on pinion. Laser align gearbox to pinion and motor to gearbox.</i> |
| 8. Services Performed |
| <i>Set pinion. Attempted to align the rest but customer decided to stop and go a different route. Customer is going to replace pinion and couplings and have us come back out.</i> |



- | |
|---------------------------------------|
| 9. Service Technician Recommendations |
|---------------------------------------|

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Approval Signatures


10. Service Technician Signature

Trevor Hall

A handwritten signature in black ink, appearing to read 'T. Hall', written over a light blue horizontal line.

11. Customer Signature

David Wolfe

A handwritten signature in black ink, appearing to read 'D. Wolfe', written over a light blue horizontal line.



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 103754
FormID: 22380009

Almatis Inc/RCP Bauxite (10014)
4701 Alcoa Road
Bauxite, AR 72011

Job Information

- | | |
|------------------------|-----------|
| 1. Hi-Speed Job Number | 103754 |
| 2. Asset Type | Ball mill |
| 3. Make | |



- | | |
|---------------------------------|--------------|
| 4. Model | |
| 5. Serial Number | |
| 6. Customer Asset ID/Asset Name | A2 Ball Mill |

Service Call Details

7. Service Objectives
To align gearbox to pinion and then motor to gearbox.

8. Services Performed
Customer installed a brand new pinion, couplings and bearings. We set the clearance on the pinion to the gear with the key stock that the customer uses to set the pinion. We then removed the shaft lock device and the brake to the gearbox and aligned the gearbox to the pinion the best we could with having to turn the ball mill. We then aligned the motor to the gearbox.



9. Service Technician Recommendations

Approval Signatures

- | | |
|----------------------------------|-------------|
| 10. Service Technician Signature | Trevor Hall |
|----------------------------------|-------------|

- | | |
|------------------------|-------------|
| 11. Customer Signature | David Wolfe |
|------------------------|-------------|

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Darrell H