## LR Field Services

Prepared for Almatis Inc/RCP Bauxite (10014)

4701 Alcoa Road Bauxite AR 72011

## **Table of Contents**



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Hi-Speed Industrial Service 7030 Ryburn Dr Millington, Tn 38053 901-873-5300

> FolderID: 102638 FormID: 19746105

## **Field Service Ticket**

Almatis Inc/RCP Bauxite (10014) 4701 Alcoa Road Bauxite, AR 72011 Performed By: Will Reaves Date Completed: 03/13/2024

| Job Information      |   |
|----------------------|---|
| 1.                   | Hi-Speed Job Number 10014                                   |
| 2.                   | Asset Type  |
| 3.                   | Make  |
| 4.                   | Model   |
| 5.                   | Serial Number   |
| 6.                   | Customer Asset ID/Asset Name                                |
| Service Call Details |   |
| 7.                   | Service Objectives  |
|                      | Check vibration on South #2 blender dc fan at building 55   |
| 8.                   | Services Performed  |
|                      | Conducted a run out check and found shaft to be bent 0.019" |
| 9.                   | Service Technician Recommendations                          |
|                      | Recommend changing fan shaft                                |
| Approval Signatures  |   |
|                      | Service Technician Signature  Customer Signature            |
| 7                    | 1)_JEWJHE   |