

LR Field Services

Prepared for Almatris Inc/RCP Bauxite (10014)

4701 Alcoa Road
Bauxite AR 72011

Table of Contents

Field Service Ticket

1.0

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 04/15/2024

Powered by [INSPECTALL](#)

Table of Contents



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

Almatis Inc/RCP Bauxite (10014)
4701 Alcoa Road
Bauxite, AR 72011

Performed By: Will Reaves
Date Completed: 04/09/2024

FolderID: 102749
FormID: 20027266

Job Information

- | | |
|---------------------------------|---------------|
| 1. Hi-Speed Job Number | 102749 |
| 2. Asset Type | |
| 3. Make | |
| 4. Model | |
| 5. Serial Number | |
| 6. Customer Asset ID/Asset Name | |

Service Call Details

- | | |
|---------------------------------------|--|
| 7. Service Objectives | <i>Check ground ore dc fan</i> |
| 8. Services Performed | <i>Checked Fan condition</i> |
| 9. Service Technician Recommendations | <i>Found problem to be inboard bearing failure</i> |

Approval Signatures

10. Service Technician Signature

11. Customer Signature

Zack Creasy