

Hi-Speed Industrial Service 7030 Ryburn Dr Millington, Tn 38053 901-873-5300

> FolderID: 152847 FormID: 20450594

Field Service Ticket

ADM 1795 DOCK ST MEMPHIS, TN 38113

Adm Dock St

Performed By: JOE SHURTZ Date Completed: 05/21/2024

Job Information		
1.	Hi-Speed Job Number	152847
2.	Asset Type	Air lanco fan
3.	Make	na
4.	Model	na
5.	Serial Number	na
6.	Customer Asset ID/Asset Name	aeration fan

Service Call Details

Service Objectives

Customer called because fan had high vibration and they wanted to check balance on it. Upon arrival I found that all the fan blades were broke on fan, the motor was making a noise so I checked vibration and determined the inboard bearing was bad on motor.

Services Performed

Checked vibration on motor

Service Technician Recommendations

Replace bearings in motor and replace the fan wheel itself as there are no blades left in the fan

Approval Signatures

Service Technician Signature

Joe Shurtz

11. Customer Signature

Simeon Wright

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.