

Hi-Speed Industrial Service 7030 Ryburn Dr Millington, Tn 38053 901-873-5300

> FolderID: 102800 FormID: 20119381

> > Р8

Field Service Ticket

Almatis Inc/RCP Bauxite (10014) 4701 Alcoa Road Bauxite, AR 72011 Performed By: Will Reaves Date Completed: 04/18/2024

Job Information 1. Hi-Speed Job Number 102800 2. Asset Type 3. Make 4. Model 5. Serial Number 6. Customer Asset ID/Asset Name Service Call Details

7. Service Objectives

Field balance #13 converter ID fan

Services Performed

Decreased imbalance from 30 to 2 mils. Fan is warped badly and production was waiting on me, maintenance was happy with 2 mils so that's where I left it



9. Service Technician Recommendations

Approval Signatures

10. Service Technician Signature



11. Customer Signature



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.