



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

DELTA PLASTICS OF THE SOUTH
3104 SOUTH MAIN STREET
STUTTGART, AR 72160

Performed By: Will Reaves
Date Completed: 04/23/2024

FolderID: 102820
FormID: 20157892

Job Information

1. Hi-Speed Job Number	102820
2. Asset Type	Mechanical Dryer
3. Make	
4. Model	
5. Serial Number	
6. Customer Asset ID/Asset Name	System 1 Mechanical Dryer #1

Service Call Details



7. Service Objectives

P7

Screens got caught in rotating assembly creating an imbalance. Field balance needed



Screen came apart and came into contact with rotor.

More places where rotor was hitting screen. New screens were installed after balance job.



8. Services Performed

P8

Took imbalance from 22 to 5 mils. Unit isn't attached to the ground so this to be below 6 is good.



9. Service Technician Recommendations

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Approval Signatures

10. Service Technician Signature



11. Customer Signature

David Harris

