

Field Service Ticket

Highland Pellets (012194) 5601 Industrial Dr North Pine Bluff, AR 71602

Hi-Speed Industrial Service 7030 Ryburn Dr Millington, Tn 38053 901-873-5300

> FolderID: 102877 FormID: 20269664

Job Information

- Hi-Speed Job Number 102877 1.
- Asset Type
- 3. Make
- 4. Model
- 5. Serial Number
- Customer Asset ID/Asset Name 6.

Service Call Details

Service Objectives

Was instructed to align disc horizontally as well as possible. Bearings are going to be changed before long and don't have time for proper alignment

Services Performed


Could not adjust vertical and the offset horizontally was 0.6 and the angle was 35.4. Disc is bolt bound.

Service Technician Recommendations

We will schedule to come back when the bearings are changed and align the entire machine tree

Approval Signatures

10. Service Technician Signature















0

P10

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.