



Field Service Ticket

FolderID: 102882
FormID: 20285734

Potlatch Warren Lumber Sawmill
(10599-POT)
810 W. Pine St.
Warren, AR 71671

Performed By: Will Reaves
Date Completed: 05/03/2024

Job Information


- | | |
|---------------------------------|--------|
| 1. Hi-Speed Job Number | 102882 |
| 2. Asset Type | |
| 3. Make | |
| 4. Model | |
| 5. Serial Number | |
| 6. Customer Asset ID/Asset Name | |

Service Call Details



7. Service Objectives
Inspect hog to see why outboard bearing is running hot.

8. Services Performed P8
Checked with vibration after the bearing was cleaned off all the water that was in it from putting water on it and found the highest point of vibration was 0.07 in/sec.



9. Service Technician Recommendations
Recommend keeping air on bearing to break in new grease. Temp should even itself out.

Approval Signatures

10. Service Technician Signature

11. Customer Signature

Aaron Robbins