



## Field Service Ticket

FolderID: 103043  
FormID: 20567847

**Highland Pellets (012194)**  
5601 Industrial Dr North  
Pine Bluff, AR 71602

### Job Information



- |                        |           |
|------------------------|-----------|
| 1. Hi-Speed Job Number | 103043    |
| 2. Asset Type          | Large Fan |
| 3. Make                | P3        |



- |                                 |           |
|---------------------------------|-----------|
| 4. Model                        |           |
| 5. Serial Number                |           |
| 6. Customer Asset ID/Asset Name | #1 ID Fan |

### Service Call Details

- |                                       |  |
|---------------------------------------|--|
| 7. Service Objectives                 | <i>Balance Fan</i>   |
| 8. Services Performed                 | <i>Checked balance on fan. Our balance box filtered out the noise/vibration from the bad bearing and showed the fan to be in balance. We balanced it down a little farther and hung a weight. Fan shaft had around .018 play up and down. Customers vibration sensor is working as should and shut the unit down due to a rough running bearing.</i> |
| 9. Service Technician Recommendations | <i>Change bearings</i>   |

### Approval Signatures

- |                                  |             |
|----------------------------------|-------------|
| 10. Service Technician Signature | Trevor Hall |
|----------------------------------|-------------|

- |                        |  |
|------------------------|--|
| 11. Customer Signature |  |
|------------------------|--|