



Field Service Ticket

FolderID: 103613
FormID: 22367288

Peco Foods

625 S. Allen Street
Batesville, AR 72501

Job Information



- | | |
|------------------------|--------------------|
| 1. Hi-Speed Job Number | 103613 |
| 2. Asset Type | Ammonia compressor |
| 3. Make | P3 |




- | | |
|---------------------------------|-------------------|
| 4. Model | |
| 5. Serial Number | |
| 6. Customer Asset ID/Asset Name | O-C-10 compressor |

Service Call Details



- | | |
|---|----|
| 7. Service Objectives | |
| <i>Install motor, align, check rotation and take vibration readings once running.</i> | |
| 8. Services Performed | P8 |
| <i>Installed motor, laser aligned, connected wiring. Tried to do test run but the motor starter is faulted. Customer is going to have starter fixed and do the rotation check and startup once it is operational.</i> | |



- | | |
|---|--|
| 9. Service Technician Recommendations | |
| <i>Once starter issue is resolved check rotation before connecting coupling and running compressor.</i> | |

Approval Signatures

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

10. Service Technician Signature

Shon Jones

A handwritten signature in black ink, appearing to be 'Shon Jones', written in a cursive style.

11. Customer Signature

Michael Beyerle

A handwritten signature in black ink, appearing to be 'Michael Beyerle', written in a cursive style.