



Hi-Speed Industrial Service  
7030 Ryburn Dr  
Millington, Tn 38053  
901-873-5300

## Field Service Ticket

FolderID: 103111  
FormID: 20706839

**Johnson Controls Inc**  
10600 Colonel Glenn Rd. Suite 200  
Little Rock, AR 72204

### Job Information



- |                        |                   |
|------------------------|-------------------|
| 1. Hi-Speed Job Number | 103111            |
| 2. Asset Type          | Compressor motors |
| 3. Make                | P8                |



- |                                 |
|---------------------------------|
| 4. Model                        |
| 5. Serial Number                |
| 6. Customer Asset ID/Asset Name |

### Service Call Details




- |                       |
|-----------------------|
| 7. Service Objectives |
| 8. Services Performed |



*Check two motors.*

*Tested both motors with Baker surge tester. Both motors passed all tests. The leads coming from the motors are somehow getting induced with voltage upwards of 30 volts DC with the breakers pulled out. Had to ground leads to be able to reconnect them without being shocked.*

P5



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



9. Service Technician Recommendations  
*Email test results to Adam.hoover@jci.com*

### Approval Signatures

10. Service Technician Signature

Trevor Hall

11. Customer Signature

Adam Hoover