



Hi-Speed Industrial Service  
7030 Ryburn Dr  
Millington, Tn 38053  
901-873-5300

## Field Service Ticket

FolderID: 103285  
FormID: 21167264

Tolm Group Inc (12758)  
210 N Moose St  
Morrilton, AR 72110

### Job Information



1. Hi-Speed Job Number





103285

2. Asset Type

Aereator

3. Make

P3




4. Model

5. Serial Number

6. Customer Asset ID/Asset Name

### Service Call Details

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

7.	Service Objectives	
	<i>Remove motor from blower and bring back to shop for inspection and repair.</i>	
8.	Services Performed	
	<i>Same as objective. Two leads from terminal box are Purple to TB1, TB2 to 2HE1:2HE2, White wire to 1HE1:1HE2.</i>	
	<i>1,7,6,12 Brown lead 1</i>	
	<i>2,4,8,10 Orange lead 2</i>	
	<i>3,5,9,11 Yellow lead 3</i>	
9.	Service Technician Recommendations	
<b>Approval Signatures</b>		
10.	Service Technician Signature	<b>Trevor Hall</b>
		
11.	Customer Signature	<b>Joel Thetford</b>
	