

Field Service Ticket

Catlett- The Tower Building (12792)

Service Objectives

Troubleshoot cooling tower vibration

323 Center Street Little Rock, AR 72201 Hi-Speed Industrial Service 7030 Ryburn Dr Millington, Tn 38053 901-873-5300

> FolderID: 103305 FormID: 21187877

Job Information 0 103305 1. Hi-Speed Job Number 2. Asset Type cooling tower fan 3. Make P3 4. Model 5. Serial Number Customer Asset ID/Asset Name cooling tower **Service Call Details** 0

8. Services Performed P8

Upon inspection of the cooling tower we found that the coupling was worn out. Customer was able to locate a new coupling. We removed the old one. We reinstalled the new coupling and laser aligned the motor to the gearbox. We had to blow elongated holes to move the motor over also.









Trevor Hall



9. Service Technician Recommendations

Approval Signatures

10. Service Technician Signature

11. Customer Signature

11. Customer Signature Ken

Her Da

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.