



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 103361
FormID: 21330180

Tyson Foods- Hope (12794)
275 Hempstead County Rd 278
Hope, AR 71802

Job Information



- | | |
|------------------------|-----------|
| 1. Hi-Speed Job Number | 103361 |
| 2. Asset Type | Fire Pump |
| 3. Make | P3 |



- | | |
|---------------------------------|-----------|
| 4. Model | |
| 5. Serial Number | |
| 6. Customer Asset ID/Asset Name | Fire pump |

Service Call Details



- | | |
|-----------------------|--|
| 7. Service Objectives | |
|-----------------------|--|

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

8. Services Performed

Laser aligned new install motor to fire pump. Motor cannot go down any further in the rear but at the coupling the alignment turned out good. Could not raise pump due to heavy piping connected to the pump. Added grease to the coupling but customer needs to add more.



9. Service Technician Recommendations

Need to put more Falk grease in coupling.

Approval Signatures

10. Service Technician Signature

Trevor Hall

11. Customer Signature

John A Peterson