



Field Service Ticket

FolderID: 103188
FormID: 21485605

Holcim (10107-FBP)
1406 Hwy 371 North
Prescott, AR 71857

Job Information

1. Hi-Speed Job Number	103188
2. Asset Type	DC Fan
3. Make	
4. Model	
5. Serial Number	
6. Customer Asset ID/Asset Name	DC Fan

Service Call Details



7. Service Objectives




Rebuild fan.

8. Services Performed

P8

Removed front intake, fan, shaft and bearings. Removed motor and motor base. Installed new motor base, bearings, shaft, fan, front intake and installed motor back onto base. Test ran the fan and field balanced. Fan ran great.





9. Service Technician Recommendations

Approval Signatures

10. Service Technician Signature

Trevor Hall

11. Customer Signature

Darren Niven