

Field Service Ticket

FolderID: 103559 FormID: 21737674

Almatis Inc/RCP Bauxite (10014) 4701 Alcoa Road Bauxite, AR 72011

Job In	ormation	0	
1.	Hi-Speed Job Number	103559	
2.	Asset Type	ID Fan	
3.	Make		P3
4.	Model		
5.	Serial Number		
6.	Customer Asset ID/Asset Name	Fan 11	
Servic	e Call Details	0	
7.	Service Objectives		
	Laser align motor and balance fan once new bearings are installed.		
8.	Services Performed		P8
	Laser aligned motor and balanced fan to 0.3 and 0.3 mils. Fan started at 1.5 mils Image: Constraint of the started start of the started start		
9.	Service Technician Recommendations		
	val Signatures Service Technician Signature	Trevor Hall	
10.			

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

11. Customer Signature

hoy Mals

Joey Mathews

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.