



Hi-Speed Industrial Service  
7030 Ryburn Dr  
Millington, Tn 38053  
901-873-5300

## Field Service Ticket

FolderID: 103836  
FormID: 22482237

**Highland Pellets (012194)**  
5601 Industrial Dr North  
Pine Bluff, AR 71602

### Job Information



- |                        |           |
|------------------------|-----------|
| 1. Hi-Speed Job Number | 103836    |
| 2. Asset Type          | Fan motor |
| 3. Make                | P8        |



- |                                 |                             |
|---------------------------------|-----------------------------|
| 4. Model                        |                             |
| 5. Serial Number                |                             |
| 6. Customer Asset ID/Asset Name | Scavenger baghouse 3 ID fan |

### Service Call Details



- |                       |
|-----------------------|
| 7. Service Objectives |
|-----------------------|
- To remove back end of motor and replace the 6318c3 bearing.*

8. Services Performed

P5

*Replaced the bearing. Old bearing had fluting and was very noisy.*



9. Service Technician Recommendations

*All four scavenger badhouse fans need either ceramic bearings on the back and a grounding brush or at least a grounding brush on the shafts.*

Approval Signatures

10. Service Technician Signature

Trevor Hall

A handwritten signature in black ink, appearing to read "Trevor Hall".

11. Customer Signature

Seth Burdine

A handwritten signature in black ink, appearing to read "Seth Burdine".

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.