

Field Service Ticket

LITTLE ROCK ZOO 1 ZOO DRIVE LITTLE ROCK, AR 72205 Hi-Speed Industrial Service 7030 Ryburn Dr Millington, Tn 38053 901-873-5300

> FolderID: 103224 FormID: 21020660

Job Information			
1.	Hi-Speed Job Number	103224	
2.	Asset Type	pump motor	
3.	Make	Baldor	
4.	Model		
5.	Serial Number		
6.	Customer Asset ID/Asset Name	Penguin pump	
Service Call Details			
7.	Service Objectives		
	Check motor and contactor.		
8.	Services Performed		
	Checked voltage to motor. 208,208,209. Checked amps. 14.5,14.3,14.5. 2000 megaohms at 1000 volts. Pulled apart contactor and it looks good. Voltage to coil on contactor is 119-good. Motor saver was set right at 208 volts so I lowered it a few volts in case another piece of equipment starts and robs power from the line causing a trip. Motor ran good.		
9.	Service Technician Recommendations		
Approval Signatures			

11. Customer Signature

10. Service Technician Signature

Colden Dostal

Trevor Hall

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.