LR Field Services

Prepared for Highland Pellets (012194)

5601 Industrial Dr North Pine Bluff AR 71602

Table of Contents



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Hi-Speed Industrial Service 7030 Ryburn Dr Millington, Tn 38053 901-873-5300

> FolderID: 102649 FormID: 19772680

Field Service Ticket

Highland Pellets (012194) 5601 Industrial Dr North Pine Bluff, AR 71602 Performed By: Will Reaves Date Completed: 03/15/2024

| Job Information | | |
|-----------------|------------------------------|--------|
| 1. | Hi-Speed Job Number | 102649 |
| 2. | Asset Type | |
| 3. | Make | |
| 4. | Model | |
| 5. | Serial Number | |
| 6. | Customer Asset ID/Asset Name | |

Service Call Details

7. Service Objectives

Balance #3 Dryer id fan

8. Services Performed

Fan was dirty in the inside, cleaned Fan and found imbalance to be at 9 mils at 750 rpm reduced imbalance to 1 mil at 750





9. Service Technician Recommendations

Approval Signatures

10. Service Technician Signature



11. Customer Signature



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.