LR Field Services

Prepared for Highland Pellets (012194)

5601 Industrial Dr North Pine Bluff AR 71602

Table of Contents

Field Service Ticket

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Field Service Ticket

FolderID: 103477 FormID: 21532869

Highland Pellets (012194) 5601 Industrial Dr North

5601 Industrial Dr North Pine Bluff, AR 71602

1.	Hi-Speed Job Number	103477
2.	Asset Type	Fan
3.	Make	
4.	Model	
5.	Serial Number	
6.	Customer Asset ID/Asset Name	
ervio	ce Call Details	
7.	Service Objectives	
	Try to troubleshoot bearing on fan.	
8.	Services Performed	
	We removed and reinstalled the bearing twice, once with one full turn as directions show and again with a little over half a rotation. We aligned motor to fan and installed new belts. After running for a couple hours the temperatures stabilized at 163 on the fan end and 215 on the pulley end. Temperature did not start to come down as we were hoping but did stabilize.	
9.	Service Technician Recommendations	
	Closely monitor bearing temps and call AirPro, the manufacturer to see if this is allowable attention. AirProfan.com	or if the fan itself needs further
ppro	oval Signatures	
	Service Technician Signature	Trevor Hall

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



11. Customer Signature

Deric Dehart

A

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.