LR Field Services

Prepared for Highland Pellets (012194)

5601 Industrial Dr North Pine Bluff AR 71602

Table of Contents

Balancing Report

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Hi-Speed Industrial Service 7030 Ryburn Dr Millington, Tn 38053 901-873-5300

FolderID: 103578

FormID: 21782122

Balancing Report

Highland Pellets (012194) 5601 Industrial Dr North

5601 Industrial Dr North Pine Bluff, AR 71602

| General | | | |
|----------------------|-------------------------|-----------|-----------------|
| 1. Job Number 103578 | | | |
| | | | |
| 2. | Report Date | | 10/01/2024 |
| 3. | Customer | | hi land pellets |
| Balancing Report | | | |
| 4. | Balance Type | | double plane |
| 5. | Balance Operating Speed | | 1199 RPM |
| 6. | Starting Measurements | | |
| | Left End | Right End | |
| | 13.1069 | 11.789 | |
| 7. | Balancing Specification | | 2.0 |
| 8. | Finished Measurements | | |
| | Left End | Right End | |
| | 2.2967 | 2.9354 | |
| 9. | List Parts Needed | | |
| | None | | |
| 10. | Service Technician | | David Maclin |
| | \mathcal{O} | | |

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.