

LR Field Services

Prepared for Kimberly Clark (10176-KCM)

500 Murphy Dr.
Maumelle AR 72113

Table of Contents

Field Service Ticket

1.0

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 04/15/2024

Powered by [INSPECTALL](#)

Table of Contents



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

Kimberly Clark (10176-KCM)
500 Murphy Dr.
Maumelle, AR 72113

Performed By: Will Reaves
Date Completed: 04/12/2024

FolderID: 102304
FormID: 20065738

Job Information

- | | |
|---------------------------------|---------------|
| 1. Hi-Speed Job Number | 102304 |
| 2. Asset Type | |
| 3. Make | |
| 4. Model | |
| 5. Serial Number | |
| 6. Customer Asset ID/Asset Name | |

Service Call Details

- | | |
|---------------------------------------|--|
| 7. Service Objectives | <i>Laser alignment on hammermill</i> |
| 8. Services Performed | <i>Used easy laser 660 to align motor to within 0.001" and checked vibration as well</i> |
| 9. Service Technician Recommendations | <i>Recommendations will be on report</i> |

Approval Signatures

10. Service Technician Signature

11. Customer Signature

Brandon Smith