

LR Field Services

Prepared for Kimberly Clark (10176-KCM)

500 Murphy Dr.
Maumelle AR 72113

Table of Contents

Balancing Report	1.0
Field Service Ticket	2.0



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Balancing Report

Kimberly Clark (10176-KCM)
500 Murphy Dr.
Maumelle, AR 72113

FolderID: 103702
FormID: 22106580

General	
1. Job Number	
2. Report Date	
3. Customer	
Balancing Report	
4. Balance Type	
5. Balance Operating Speed	
6. Starting Measurements	
Left End	Right End
7. Balancing Specification	
8. Finished Measurements	
Left End	Right End
9. List Parts Needed	
10. Service Technician	

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 103702
FormID: 22106581

Kimberly Clark (10176-KCM)
500 Murphy Dr.
Maumelle, AR 72113

Job Information

- Hi-Speed Job Number **103702**
- Asset Type **CM3 fan**



- Make
- Model
- Serial Number
- Customer Asset ID/Asset Name **CM3 splitter fan**

Service Call Details

- Service Objectives
Balance fan.
- Services Performed
Balanced fan from 1.5 mils down to 0.5.
- Service Technician Recommendations

Approval Signatures

- Service Technician Signature **Trevor Hall**

- Customer Signature **Michael Woole**

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

