

LR Field Services

Prepared for Mercer Conway

1800 Sturgis Road
Conway AR 72034

Table of Contents

Field Service Ticket

1.0

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 03/26/2024

Powered by [INSPECTALL](#)

Table of Contents



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

Mercer Conway
1800 Sturgis Road
Conway, AR 72034

FolderID: 102617
FormID: 19781037

Job Information

- | | |
|------------------------|---------------------|
| 1. Hi-Speed Job Number | 102617 |
| 2. Asset Type | dust collector fans |
| 3. Make | |



- | | |
|---------------------------------|--------------------------------|
| 4. Model | |
| 5. Serial Number | |
| 6. Customer Asset ID/Asset Name | dust collector fans 1, 2 and 3 |

Service Call Details


7. Service Objectives

Balance fans

8. Services Performed

*Fan 3 started at 1.1 and 2.0. Ended at 0.2 and 0.4.
All bolts for cover on fan 3 are stripped
Fan 2 started at 3.5 and 3.4. Ended at 0.9 and 0.6. Had to clean off the fan by scraping.
Fan 1 started at 2.2 and 2.3. Ended at 0.3 and 0.4*

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



9. Service Technician Recommendations

Approval Signatures

10. Service Technician Signature

Trevor Hall



11. Customer Signature

Jacob

