

# LR Field Services

Prepared for Murray Hydro Plant (10772-MHP)

8th St. & Main St.  
N.Little Rock AR 72115

# Table of Contents

Field Service Ticket	1.0
Field Service Ticket	2.0



Hi-Speed Industrial Service  
7030 Ryburn Dr  
Millington, Tn 38053  
901-873-5300

## Field Service Ticket

FolderID: 103549  
FormID: 21733499

### Murray Hydro Plant (10772-MHP)

8th St. & Main St.  
N.Little Rock, AR 72115

#### Job Information




1. Hi-Speed Job Number	103549
2. Asset Type	Generator
3. Make	
4. Model	
5. Serial Number	
6. Customer Asset ID/Asset Name	Unit 2

#### Service Call Details

7. Service Objectives	<i>Perform PDMA on unit 2</i>
8. Services Performed	<i>Performed PDMA on unit 2. Checked the rotor and the stator separately. Brushes looked good so we did not touch them.</i>



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.





9. Service Technician Recommendations

*Unit is getting very dirty inside and covered in carbon. Unit is going to need to be cleaned at some point. Maybe dry ice blast.*

**Approval Signatures**

10. Service Technician Signature

**Thomas Hankins**

11. Customer Signature

**Trevor Hall**





Hi-Speed Industrial Service  
7030 Ryburn Dr  
Millington, Tn 38053  
901-873-5300

## Field Service Ticket

FolderID: 103549  
FormID: 21924728

**Murray Hydro Plant (10772-MHP)**  
8th St. & Main St.  
N.Little Rock, AR 72115

### Job Information

1. Hi-Speed Job Number	103549
2. Asset Type	Generator
3. Make	
4. Model	
5. Serial Number	
6. Customer Asset ID/Asset Name	Unit 1


### Service Call Details

7. Service Objectives  
*PDMA generator stator and rotor.*
8. Services Performed  
*Same as objective.*





Before

Swapped



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



9. Service Technician Recommendations

*Motor is full of carbon from the brushes. Generator will eventually need to be cleaned like the other unit.*

**Approval Signatures**

10. Service Technician Signature

**Trevor Hall**

11. Customer Signature

**Jackie Halsey**