LR Field Services

Prepared for Potlatch-Ola

729 Hwy 10 East Ola AR 72853

Table of Contents



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Hi-Speed Industrial Service 7030 Ryburn Dr Millington, Tn 38053 901-873-5300

> FolderID: 102407 FormID: 19190085

Field Service Ticket

Potlatch-Ola 729 Hwy 10 East Ola, AR 72853 Performed By: Will Reaves Date Completed: 02/04/2024

Job Information

- 1. Hi-Speed Job Number 102407
- 2. Asset Type hog
- Make





- 4. Model
- 5. Serial Number
- 6. Customer Asset ID/Asset Name Hog 2

Service Call Details

7. Service Objectives

Balance hog. Aligned motors to drive shaft and checked balance on hog. Balance was found to be 0.4 and 0.1 mils.

8. Services Performed

Customer will get ahold of us when they are ready. They have a couple issues to resolve first. Side-note/Rotor rotates at 660 rpm





 Service Technician Recommendations N/A

Approval Signatures

10. Service Technician Signature

Trevor Hall

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

11. Customer Signature

Chad Dozier

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.